

# SL SHOP (Sales & Service) Ltd

# Vehicle Health Check

## CUSTOMER DETAIL

H  
Tel M  
W

## VEHICLE DETAIL

Make Mercedes-Benz  
Model  
Registration C769FAH  
Chassis No  
Mileage 86805

## VHC NO

8063

Date 2022-08-12  
Service Advisor  
MOT Due  
Inspected By Russell Owens

Comments / Recommendations		Net	VAT	Total
<b>Initial Road Test 00IRT</b>				
A	Engine performance / smoke / noises	Slightly lumpy at idle		
G	Brake performance / spongy / pulling left or right			
G	Steering in straight position / feel / noises			
A	Check operation of warning lights 54585	Washer bottle for wiper system low warning light not coming on with ignition.		
G	Check operation of wipers and washers 86000			
G	Check operation of horn 54105			
G	Check operation of parking brake 42120			
<b>lights 82000</b>				
G	Check operation of front external lights 82195			
G	Check operation of rear external lights 82225			
<b>Interior 91000</b>				
G	Check seat and seat belt operation 91090			
A	Check interior lights 82165	Footwell illumination inoperative (when manipulating door contact switch on drivers side illumination will come on, once switch is released illumination becomes inoperative)		
G	Heater motor operation 83135			
G	Radio and aerial operation 82345			
<b>Engine Bay 18000</b>				
G	Antifreeze strength 50000			
G	Remove heater box lid-check bulkhead 62015			
G	Check battery condition 54080			
G	Check charging Volts 15030			
G	Check G/Box oil level 18000			
G	Check engine oil level / condition 18000			
G	Check for fuel leaks 07075			
G	Check brake fluid level / condition 42000			
<b>Under Vehicle 00UV</b>				
G	Check drop links 32060			
G	Check front wishbones 33030			
G	Check shock absorbers 32000			
G	Check engine mountings 22010			
A	Check subframe bushes 33010	Rear subframe bushes appear collapsed with extensive gap between retaining clamp and bottom of bushes, movement can be seen on engine subframe. Retaining bolts and clamp appear in new condition. Suggest investigation into excessive gap at mounting.		

# SL SHOP (Sales & Service) Ltd

# Vehicle Health Check

## CUSTOMER DETAIL

H  
Tel M  
W

## VEHICLE DETAIL

Make **Mercedes-Benz**  
Model  
Registration **C769FAH**  
Chassis No  
Mileage **86805**

## VHC NO

8063

## Date

2022-08-12

## Service Advisor

## MOT Due

## Inspected By

Russell Owens

Comments / Recommendations		Net	VAT	Total
A	Check for general oil leaks 18000 Small leak around bottom of gearbox, looks to be rear main seal as oil can be seen inside gearbox towards rear of engine			
A	Check propshaft couplings condition 41015 Rear propshaft coupling perished and cracking			
A	Check fuel pump pipes/filter package 47045 All rubber pipes are slightly perished but no leaks. Fuel package mounting bracket corroded, advise changing both the fuel package bracket and mounting bracket			
G	Check exhaust system condition 14060			
R	General underbody corrosion / Waxoyl 61000 OSF chassis leg has previously been repaired but poorly, its been covered in seam sealer and the corrosion is still present underneath the ABS pump. Reconstruction of inner arch to chassis leg needed, reconstruction of anti roll bar bracket needed and possibly underneath ABS pump. 25hours required due to within 30 cm of a suspension component however further time may be required upon removal of ABS pump. NSF chassis leg corroded inside and advise cleaning down before it gets worse 2 hours. OSR arch to boot is severely corroded and is within 30 cm of a suspension component, fabrication is needed and 4 hours required however may increase once work is started as unsure how much corrosion is below the surface. Slight surface corrosion around OSR anti roll bar. Slight surface corrosion around OSR chassis leg.			
G	Visual check on brake pads and discs 42000			
G	Check rear drive shafts/boots 35030			
<b>Soft Top Check 77000</b>				
G	Check soft top open/closure/catch mechanism 7700			
<b>Water Test 00WT</b>				
G	Check bulkhead for leaks			
G	Check window/door seals for leaks			
G	Check boot/rear lights for leaks			
<b>Total</b>		0.00	0.00	0.00

Tyres	Tread (mm)	Manufacturer	Size	Comments/Recommendations
G N/S Front				
G N/S Rear				
G O/S Front				
G O/S Rear				
G Spare				

Brakes	Drums	Pads	Discs	Comments/Recommendations
	% Remaining		% Remaining	
N/S Front	N			
N/S Rear	N			
O/S Front	N			
O/S Rear	N			

## Photos

**Customer Signature** \_\_\_\_\_ The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.