SL SHOP (Sales & Service) Ltd

Vehicle Health Check

CUSTOMER DETAIL

VEHICLE DETAIL

VHC NO 9912

MOT Due

Mr Ian Downie

Make Mercedes-Benz

Date 2023-05-16

H 01242 673 200

Model SI

Service Advisor Russell Owens

Tel M 07785 392 075

Registration E499SEL

21/12/2023

W

Chassis No WDB1070472A083046

Inspected By m - Callum Harkness

Mileage 137416

| | Comments / Recommendations Net VAT Total | | | | | | | |
|-------------------------|--|--|---|--|--|--|--|--|
| Initial Road Test 00IRT | | | | | | | | |
| G | Engine performance / smoke / noises | | | | | | | |
| G | Brake performance / spongy / pulling left or right | | | | | | | |
| G | Steering in straight position / feel / noises | | | | | | | |
| G | Check operation of warning lights 54585 | | | | | | | |
| G | Check operation of wipers and washers 86000 | | | | | | | |
| G | Check operation of horn 54105 | | | | | | | |
| G | Check operation of parking brake 42120 | | | | | | | |
| liç | jhts 82000 | | | | | | | |
| G | Check operation of front external lights 82195 | | | | | | | |
| G | Check operation of rear external lights 82225 | | | | | | | |
| In | terior 91000 | | | | | | | |
| G | Check seat and seat belt operation 91090 | | | | | | | |
| G | Check interior lights 82165 | | | | | | | |
| G | Heater motor operation 83135 | | | | | | | |
| G | Radio and aerial operation 82345 | | | | | | | |
| E | ngine Bay 18000 | | | | | | | |
| G | Antifreeze strength 50000 | -37 degrees of protection | | | | | | |
| R | Remove heater box lid- check bulkhead 62015 | Bulkhead is heavily corroded. Requires a full bulkhead resto. | | | | | | |
| G | Check battery condition 54080 | | | | | | | |
| G | Check charging Volts 15030 | | | | | | | |
| G | Check G/Box oil level 18000 | | | | | | | |
| G | Check engine oil level / condition 18000 | | | | | | | |
| G | Check for fuel leaks 07075 | | | | | | | |
| G | Check brake fluid level / condition 42000 | | | | | | | |
| U | Under Vehicle 00UV | | | | | | | |
| G | Check drop links 32060 | | | | | | | |
| G | Check front wishbones 33030 | | | | | | | |
| G | Check shock absorbers 32000 | | | | | | | |
| G | Check engine mountings 22010 | | | | | | | |
| G | Check subframe bushes 33010 | | | | | | | |
| A | Check for general oil leaks 18000 | Signs of an oil leak from rear of engine, needs cleaning down and investigating. | _ | | | | | |
| G | Check propshaft couplings condition 41015 | | | | | | | |

SL SHOP (Sales & Service) Ltd

Vehicle Health Check

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 9912

Mr Ian Downie Make Mercedes-Benz Date 2023-05-16

 H
 01242 673 200
 Model
 SI
 Service Advisor
 Russell Owens

 Tel
 M
 07785 392 075
 Registration
 E499SEL
 MOT Due
 21/12/2023

W Chassis No WDB1070472A083046 Inspected By m - Callum Harkness

Mileage 137416

| | Comments / Recommendations | Net | VAT | Total |
|--|---|------|------|-------|
| Check fuel pump pipes/filter package 47045 | Metal fuel line at pump package has corrosion. | | | |
| Check exhaust system condition 14060 | | | | |
| General underbody corrosion / Waxoyl 61000 | Signs of corrosion under the underseal at the rear chassis legs. Patches of light surface corrosion above rear subframe assembly. | | | |
| Visual check on brake pads and discs 42000 | | | | |
| Check rear drive shafts/boots 35030 | | | | |
| Soft Top Check 77000 |) | | | |
| Check soft top open/closure/catch mechanism 7700 | | | | |
| Water Test 00WT | | | | |
| Check bulkhead for leaks | Bulkhead requires full restoration | | | |
| Check window/door seals for leaks | A pillar seals are showing age related deterioration. | | | |
| Check boot/rear lights for leaks | | | | |
| | Total: | 0.00 | 0.00 | 0.00 |

| Tyres | Tread (mm) Manufacturer Size | | | Comments/Recommendations | | |
|-------------|------------------------------|--|--|---------------------------------|--|--|
| G N/S Front | 7.0 | | | | | |
| G N/S Rear | 6.0 | | | | | |
| G O/S Front | 7.0 | | | | | |
| G O/S Rear | 6.0 | | | | | |
| G Spare | 5.0 | | | | | |

| | | % Remaining | | % Remaining | |
|-----------|---|-------------|----|-------------|----|
| N/S Front | N | G | 95 | G | 95 |
| N/S Rear | N | G | 60 | G | 80 |
| O/S Front | N | G | 95 | G | 95 |
| O/S Rear | N | G | 60 | G | 80 |

Discs

Photos

Brakes

Remove heater box lid-check bulkhead

Drums Pads



Check for general oil leaks 18000 -



Check fuel pump pipes/filter package

Comments/Recommendations



| Customer Signature_ | The work outlined in this report has been brought to my attention |
|---------------------|---|
| • | |

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.