SL SHOP (Sales & Service) Ltd

Vehicle Health Check

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 7232

Mr Tex CrampinMakeMercedes-BenzDate2022-05-06HModel230Service AdvisorRussell Owens

 Tel
 M
 Registration
 ORR90M
 MOT Due
 02/09/2021

 W
 Chassis No
 115-017-2D005231
 Inspected By
 m - Simon Wood

Mileage 33457

	Comments / Recommendations	Net	VAT	Tota
itial Road Test 00IR	Т			
Engine performance / smoke / noises				
Brake performance / spongy / pulling left or right	Brakes pull to the left under heavy braking.			
Steering in straight position / feel / noises				
Check operation of warning lights 54585				
Check operation of wipers and washers 86000	Wipers work fine. The off side wiper jet is blocked.			
Check operation of horn 54105				
Check operation of parking brake 42120				
ghts 82000				
Check operation of front external lights 82195				
Check operation of rear external lights 82225				
terior 91000				
Check seat and seat belt operation 91090				
Check interior lights 82165				
Heater motor operation 83135				
Radio and aerial operation 82345	Manual aerial Works and radio switches on but the radio will not pick up a radio station.			
ngine Bay 18000				
Antifreeze strength 50000	-34 to -37 degrees c.			
Remove heater box lid- check bulkhead 62015				
Check battery condition 54080				
Check charging Volts 15030				
Check G/Box oil level 18000				
Check engine oil level / condition 18000				
Check for fuel leaks 07075				
Check brake fluid level / condition 42000	Temperature ok >320 degrees			
nder Vehicle 00UV				
Check drop links 32060				
Check front wishbones 33030				
Check shock absorbers 32000				
Check engine mountings 22010				
Check subframe bushes 33010				
Check for general oil leaks 18000	Front and lower Engine is sited in oil. Would advice clean down and monitoring. Oil leaking from the differential. Possible moisture from the breather. Possibly diff end plate. Recommend cleaning down and monitor.			

SL SHOP (Sales & Service) Ltd

Vehicle Health Check

CUSTOMER DETAIL VEHICLE DETAIL VHC NO Mercedes-Benz Mr Tex Crampin Make Date 2022-05-06 230 Model Н Service Advisor Russell Owens ORR90M Tel Registration MOT Due 02/09/2021 M W Chassis No 115-017-2D005231 Inspected By m - Simon Wood Mileage 33457

	Net	VAT	Total	
Check propshaft couplings condition 41015	Comments / Recommendations Prop shaft coupling are good but prop centre barring x2 are badly worn. Advice replacing.			
Check fuel pump pipes/filter package 47045	Flexible pipe by the tank hard and cracking. Not leaking on present test but possible leaks in the future.			
Check exhaust system condition 14060				
General underbody corrosion / Waxoyl 61000	Heavily coated in a black tape substance.			
Visual check on brake pads and discs 42000	N/S/F brake is binding. Cars pulls to the left on braking. Front brake hoses both sides have slight cracks in them advise replacing them.			
Check rear drive shafts/boots 35030				
Soft Top Check 77000)			
Check soft top open/closure/catch mechanism 7700	No soft top.			
Water Test 00WT			•	
Check bulkhead for leaks				
Check window/door seals for leaks				
Check boot/rear lights for leaks				
·	Total	0.00	0.00	0.00

Tyres	Tread (mm) Manufact	turer Size	Comments/Recommendations
G N/S Front	7.0			
G N/S Rear	7.0			
G O/S Front	7.0			
G O/S Rear	6.0			
G Spare	6.0			
Brakes	Drums	Pads	Discs	Comments/Recommendations
Brakes	Drums	Pads % Remaining	Discs % Remaining	Comments/Recommendations
N/S Front	Drums			Comments/Recommendations
N/S Front		% Remaining	% Remaining	Comments/Recommendations
	N	% Remaining G 60	% Remaining G 90	Comments/Recommendations

Customer Signature	The work outlined in this report has been brought to my attention
•	

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.