SL SHOP (Sales & Service) Ltd

Make

Model

Mileage

Chassis No

CUSTOMER DETAIL

07841 381 386

Mr Craig Scorer

Н

Μ

W

Tel

VEHICLE DETAIL

Registration D210WCF

Mercedes-Benz

WDB1070412A058332

SL Class

42761

Vehicle Health Check

7277

VHC NO

Date
Service Advis
MOT Due

Inspected By

2022-05-10 Sor Russell Owens 19/04/2023 m - Josh Lewis

G	tial Road Test 00IR	1		
	/ noises			
	Brake performance / spongy / pulling left or right			
	Steering in straight position / feel / noises			
	Check operation of warning lights 54585	No handbrake warning light-mot fail		
	Check operation of wipers and washers 86000	Wiper Park position needs adjusting- when parked they obstruct passenger view		
	Check operation of horn 54105			
	Check operation of parking brake 42120			
lig	hts 82000			
	Check operation of front external lights 82195			
	Check operation of rear external lights 82225			
Inte	erior 91000			
	Check seat and seat belt operation 91090	Drivers seat has movement due to missing the plastic tabs in the runners		
	•	Drivers seat has slight wear on bolster		
Α	Check interior lights 82165	When opening passenger door- welcome light doesn't work due to faulty door switch		
	Heater motor operation 83135			
	Radio and aerial operation 82345			
Α	A pillar seals	O/s a pillar seal has slight perishing and cracks		
Α	Door seals	Both door seals have slight perishing		
Α	Woolpack	The 3 piece dashboard wood pack is a different shade to the woodpacks surrounding gear selector and radio fascia		
	Central locking	Central locking inop when locking passenger door		
En	gine Bay 18000		1	1
G	Antifreeze strength 50000			
	Remove heater box lid- check bulkhead 62015	Advise waxoyl on the bulkhead to maintain excellent condition		
	Check battery condition 54080	Battery insecure due to clamp being fitted upside down		
G	Check charging Volts 15030			
G	Check G/Box oil level 18000			
	Check engine oil level / condition 18000			
G	Check for fuel leaks 07075			
	Check brake fluid level / condition 42000	Brake fluid level above maximum		
А	Fan cowling	Fan cowling is loose and hitting crank pulley		
Un	der Vehicle 00UV			
G	Check drop links 32060			
	Check front wishbones 33030			

SL SHOP (Sales & Service) Ltd

CUSTOMER DETAIL

VEHICLE DETAIL

Vehicle Health Check

VHC NO

MOT Due

Inspected By

Date

Mr Cr	raig S	corer	
	Н		
Tel	Μ	07841 381 386	
	W		

Make Mercedes-Benz Model SL Class Registra Chassis Mileage

tion	D210WCF
No	WDB1070412A058

42761

8332			

2022-05-10 Service Advisor Russell Owens 19/04/2023

7277

m - Josh Lewis

	Comments / Recommendations	Net	VAT	Total
G Check shock absorbers 32000				
G Check engine mountings 22010				
G Check subframe bushes 33010				
Check for general oil leaks 18000	Rear main seal leaking Power steering pump leakingPower steering box leaking Pinion seal leaking and end plate of diff is starting to mist			
G Check propshaft couplings condition 41015				
G Check fuel pump pipes/filter package 47045				
Check exhaust system condition 14060	Exhaust rubbers need replacing due to perishing			
General underbody corrosion / Waxoyl 61000	O/s Front chassis leg starting to bubble- clean down and treatFront towing eye needs cleaning down due to surface corrosion			
Visual check on brake pads and discs 42000				
G Check rear drive shafts/boots 35030				
R Anti roll bar	O/s Front anti roll bar mounting loose causing a clunking noise over bumps			
Lower arm ball joints	Lower arm ball joint gaiters split			
Soft Top Check 77000)			
Check soft top open/closure/catch mechanism 7700	Soft top windows have slight cracks and splits.			
Water Test 00WT				
Check bulkhead for leaks				
Check window/door seals for leaks	Slight water ingress from n/s soft top seal			
Check boot/rear lights for leaks				
	Total	0.00	0.00	0.00

Tyres	Tread (mm) Ma	nufacturer Size	Comments/Recommendations
G N/S Front	7.0		
G N/S Rear	6.0		
G O/S Front	7.0		
G O/S Rear	6.0		
G Spare	5.0		

		% Re	emaining	% Re	emaining
N/S Front	N	G	95	G	90
N/S Rear	N	G	90	G	90
O/S Front	N	G	95	G	90
O/S Rear	N	G	90	G	90

Customer Signature

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.