SL SHOP (Sales & Service) Ltd

W

Vehicle Health Check

Russell Owens

Inspected By

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 7964

 INTERNAL
 Make
 Mercedes-Benz
 Date
 2022-07-29

 H
 Model
 SL Class
 Service Advisor
 Russell Owens

 Tel
 M
 Registration
 D707LNF
 MOT Due
 26/08/2022

1070412A050647

Chassis No Mileage

	Comments / Recommendations	Net	VAT	Tota
itial Road Test 00IR	Т			
Engine performance / smoke / noises				
Brake performance / spongy / pulling left or right				
Steering in straight position / feel / noises	Steering wheel off to the left, needs adjusting one spline to the right			
Check operation of warning lights 54585				
Check operation of wipers and washers 86000				
Check operation of horn 54105				
Check operation of parking brake 42120				
hts 82000				
Check operation of front external lights 82195				
Check operation of rear external lights 82225				
terior 91000		•	•	
Check seat and seat belt operation 91090				
Check interior lights 82165	OS footwell light not working, suspect bulb.			
Heater motor operation 83135				
Radio and aerial operation 82345				
ngine Bay 18000			1	
Antifreeze strength 50000				
Remove heater box lid- check bulkhead 62015	Recommend clean out of bulkhead & apply cavity wax to protect against any future corrosion			
Check battery condition 54080				
Check charging Volts 15030				
Check G/Box oil level 18000				
Check engine oil level / condition 18000				
Check for fuel leaks 07075				
Check brake fluid level / condition 42000				
nder Vehicle 00UV				
Check drop links 32060	Anti roll bar link bushes are starting to split,ok for now but would recommend replacement if subframe bushes are changed			
Check front wishbones 33030				
Check shock absorbers 32000				
Check engine mountings 22010	Engine mounts perished & split,recommend with subframe bushes			
Check subframe bushes 33010	Subframe bushes have gone weak & sunk,recommend replacement			

SL SHOP (Sales & Service) Ltd

Vehicle Health Check

The work outlined in this report has been brought to my attention

CUSTOMER DETAIL VEHICLE DETAIL VHC NO Make Mercedes-Benz **INTERNAL** Date 2022-07-29 Model SL Class Service Advisor Russell Owens Н Registration D707LNF 26/08/2022 Tel M MOT Due W Chassis No 1070412A050647 Inspected By **Russell Owens** Mileage VAT **Total** Comments / Recommendations Net Check for general oil leaks Timing case seal is leaking, advise replacement of seal, rocker gasket & camshaft seal. Due to the amount of oil over the front of the engine it is 18000 possible that the front crank seal may be leaking. Would recommend replacing front timing seal, clean down old oil from engine & monitor crank seal for leakage Check propshaft couplings condition 41015 Check fuel pump pipes/filter Rubber hose from fuel filter to main metal supply line is incorrectly routed & package 47045 is rubbing on spare wheel well, needs routing correctly Check exhaust system condition 14060 General underbody corrosion / Waxoyl 61000 Visual check on brake pads and discs 42000 Check rear drive shafts/boots 35030 Soft Top Check 77000 Check soft top open/closure/catch mechanism 7700 **Water Test 00WT** Check bulkhead for leaks Check window/door seals for leaks Check boot/rear lights for leaks 0.00 0.00 0.00 **Total** Tread (mm) Manufacturer Size **Comments/Recommendations Tyres** N/S Front N/S Rear O/S Front O/S Rear Spare **Drums Pads Discs Comments/Recommendations Brakes** % Remaining % Remaining N/S Front Ν N/S Rear Ν O/S Front Ν O/S Rear Ν **Photos**

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.

Customer Signature