

SL SHOP (Sales & Service) Ltd

Vehicle Health Check

CUSTOMER DETAIL

Mr Andrew Jagger
H
Tel M 07850 426 685
W

VEHICLE DETAIL

Make Mercedes-Benz
Model 600
Registration BNZ1612
Chassis No WDB1400572A070738
Mileage 67804

VHC NO

7619

Date 2022-06-20
Service Advisor Russell Owens
MOT Due 25/09/2022
Inspected By m - Stefan Rich

Comments / Recommendations		Net	VAT	Total
Initial Road Test 00IRT				
G	Engine performance / smoke / noises			
A	Brake performance / spongy / pulling left or right	Slightly spongy pedal		
G	Steering in straight position / feel / noises			
G	Check operation of warning lights 54585			
G	Check operation of wipers and washers 86000			
G	Check operation of horn 54105			
G	Check operation of parking brake 42120			
R	Headlight wash wipe	Headlight washers and wipers don't work at all		
lights 82000				
G	Check operation of front external lights 82195			
G	Check operation of rear external lights 82225			
Interior 91000				
G	Check seat and seat belt operation 91090			
G	Check interior lights 82165			
G	Heater motor operation 83135			
G	Radio and aerial operation 82345			
Engine Bay 18000				
G	Antifreeze strength 50000	-23°C		
N/A	Remove heater box lid-check bulkhead 62015			
G	Check battery condition 54080			
G	Check charging Volts 15030			
G	Check G/Box oil level 18000			
G	Check engine oil level / condition 18000			
G	Check for fuel leaks 07075			
G	Check brake fluid level / condition 42000			
Under Vehicle 00UV				
G	Check drop links 32060			
G	Check front wishbones 33030			
G	Check shock absorbers 32000			
G	Check engine mountings 22010			
G	Check subframe bushes 33010			
G	Check for general oil leaks 18000			

SL SHOP (Sales & Service) Ltd

Vehicle Health Check

CUSTOMER DETAIL

Mr Andrew Jagger
H
Tel M 07850 426 685
W

VEHICLE DETAIL

Make Mercedes-Benz
Model 600
Registration BNZ1612
Chassis No WDB1400572A070738
Mileage 67804

VHC NO

7619

Date 2022-06-20
Service Advisor Russell Owens
MOT Due 25/09/2022
Inspected By m - Stefan Rich

Comments / Recommendations		Net	VAT	Total
G	Check propshaft couplings condition 41015			
G	Check fuel pump pipes/filter package 47045			
G	Check exhaust system condition 14060			
G	General underbody corrosion / Waxoyl 61000			
G	Visual check on brake pads and discs 42000			
G	Check rear drive shafts/boots 35030			
Soft Top Check 77000				
N/A	Check soft top open/closure/catch mechanism 7700			
Water Test 00WT				
G	Check bulkhead for leaks			
G	Check window/door seals for leaks			
G	Check boot/rear lights for leaks			
Total		0.00	0.00	0.00

Tyres	Tread (mm)	Manufacturer	Size	Comments/Recommendations
G N/S Front	7.0			
G N/S Rear	6.0			
G O/S Front	7.0			
G O/S Rear	6.0			
G Spare	7.0			

Brakes	Drums	Pads	Discs	Comments/Recommendations
		% Remaining	% Remaining	
N/S Front	N	G 45	G 85	
N/S Rear	N	A 40	G 85	
O/S Front	N	G 45	G 85	
O/S Rear	N	A 40	G 85	

Photos

Customer Signature _____ The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.