

SL SHOP (Sales & Service) Ltd

Vehicle Health Check

CUSTOMER DETAIL

Mr Guy Fitzgerald
H
Tel M 07990 574 477
W

VEHICLE DETAIL

Make Mercedes-Benz
Model SL Class
Registration N410AKL
Chassis No WDB1290632F128592
Mileage

VHC NO

7879

Date

2022-07-21

Service Advisor

MOT Due

Inspected By

m - Stefan Rich

Comments / Recommendations		Net	VAT	Total
Initial Road Test 00IRT				
G	Engine performance / smoke / noises			
A	Brake performance / spongy / pulling left or right	Brake pedal feels very spongy and pulls slightly to the left		
A	Steering in straight position / feel / noises	Steering wheel slightly to the left		
G	Check operation of warning lights 54585			
A	Check operation of wipers and washers 86000	Headlight washers Don't work		
G	Check operation of horn 54105			
G	Check operation of parking brake 42120			
lights 82000				
A	Check operation of front external lights 82195	NSF fog light inop		
G	Check operation of rear external lights 82225			
Interior 91000				
N/A	Check seat and seat belt operation 91090			
A	Check interior lights 82165	Header rail lights inop		
G	Heater motor operation 83135			
A	Radio and aerial operation 82345	Radio turns on but aerial doesn't work		
A	Sun visors	Both mirror covers on the sun visors are broken, and the corner plastic peaces are broken on the passengers side and missing on the drivers side		
Engine Bay 18000				
G	Antifreeze strength 50000			
N/A	Remove heater box lid-check bulkhead 62015			
G	Check battery condition 54080			
G	Check charging Volts 15030			
G	Check G/Box oil level 18000			
A	Check engine oil level / condition 18000	Engine oil only half full		
G	Check for fuel leaks 07075			
G	Check brake fluid level / condition 42000			
A	Bonnet insulation	Bonnet Insulation coming unstuck from bonnet		
Under Vehicle 00UV				
N/A	Check drop links 32060			
G	Check front wishbones 33030			
G	Check shock absorbers 32000			
G	Check engine mountings 22010			
A	Check subframe bushes 33010	Rear subframe bushes look very perished		

SL SHOP (Sales & Service) Ltd

Vehicle Health Check

CUSTOMER DETAIL

Mr Guy Fitzgerald
H
Tel M 07990 574 477
W

VEHICLE DETAIL

Make Mercedes-Benz
Model SL Class
Registration N410AKL
Chassis No WDB1290632F128592
Mileage

VHC NO

7879

Date

2022-07-21

Service Advisor

MOT Due

Inspected By

m - Stefan Rich

Comments / Recommendations		Net	VAT	Total
R	Check for general oil leaks 18000	Very excessive oil leaks		
G	Check propshaft couplings condition 41015			
G	Check fuel pump pipes/filter package 47045			
G	Check exhaust system condition 14060			
A	General underbody corrosion / Waxoyl 61000	Rear subframe very corroded		
G	Visual check on brake pads and discs 42000			
G	Check rear drive shafts/boots 35030			
Soft Top Check 77000				
G	Check soft top open/closure/catch mechanism 7700	Soft top operates as it should and seals but there are little tears appearing in the fabric at the very back		
Water Test 00WT				
G	Check bulkhead for leaks			
G	Check window/door seals for leaks			
G	Check boot/rear lights for leaks			
		Total	0.00	0.00

Tyres	Tread (mm)	Manufacturer	Size	Comments/Recommendations
G N/S Front	5.0			
G N/S Rear	8.0			
G O/S Front	4.0			
G O/S Rear	8.0			
G Spare	7.0			

Brakes	Drums	Pads	Discs	Comments/Recommendations
		% Remaining	% Remaining	
N/S Front	N	G 50	G 80	
N/S Rear	N	G 50	G 80	
O/S Front	N	G 50	G 80	
O/S Rear	N	G 50	G 80	

Photos

Customer Signature _____ The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.