



# SL SHOP (Sales & Service) Ltd

# Vehicle Health Check

## CUSTOMER DETAIL

Mr Nick Hull  
H  
Tel M 07812 540 247  
W

## VEHICLE DETAIL

Make Mercedes-Benz  
Model SI  
Registration F92AOC  
Chassis No WDB1070412A094917  
Mileage 105348

## VHC NO

7965

## Date

2022-07-29

## Service Advisor

## MOT Due

20/03/2014

## Inspected By

m - Simon Wood

Tyres	Tread (mm)	Manufacturer	Size	Comments/Recommendations
G N/S Front	7.0			
G N/S Rear	6.0			N/s rear tyre has a screw in it
G O/S Front	7.0			
G O/S Rear	6.0			
G Spare	6.0			


Brakes	Drums	Pads	Discs	Comments/Recommendations
		mm Remaining	mm Remaining	
N/S Front	N	G 90	G 90	
N/S Rear	N	G 95	G 90	
O/S Front	N	G 90	G 90	
O/S Rear	N	G 95	G 90	

## Photos

Axles - Image 1 of 1



Brakes - Image 1 of 1



N/S Rear



**Customer Signature** \_\_\_\_\_

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.