

SL SHOP (Sales & Service) Ltd

Vehicle Health Check

CUSTOMER DETAIL

Mr Michael Bulgin
 H 01308 427651
 Tel M 07957 856 740
 W

VEHICLE DETAIL

Make Mercedes-Benz
 Model SL Class
 Registration C81HMD
 Chassis No WDB1070472A042497
 Mileage 90326

VHC NO

8891

Date 2022-11-14
 Service Advisor
 MOT Due 18/08/2023
 Inspected By Russell Owens

Comments / Recommendations		Net	VAT	Total
Initial Road Test 00IRT				
G	Engine performance / smoke / noises			
G	Brake performance / spongy / pulling left or right			
G	Steering in straight position / feel / noises			
G	Check operation of warning lights 54585			
G	Check operation of wipers and washers 86000			
G	Check operation of horn 54105			
G	Check operation of parking brake 42120			
lights 82000				
G	Check operation of front external lights 82195			
G	Check operation of rear external lights 82225			
Interior 91000				
G	Check seat and seat belt operation 91090			
A	Check interior lights 82165	Header rail lights not working		
G	Heater motor operation 83135			
G	Radio and aerial operation 82345			
Engine Bay 18000				
G	Antifreeze strength 50000			
A	Remove heater box lid-check bulkhead 62015	Small signs of surface corrosion, would benefit from a quick clean up and waxoyl		
G	Check battery condition 54080			
G	Check charging Volts 15030			
G	Check G/Box oil level 18000			
G	Check engine oil level / condition 18000			
G	Check for fuel leaks 07075			
G	Check brake fluid level / condition 42000			
Under Vehicle 00UV				
G	Check drop links 32060			
G	Check front wishbones 33030			
G	Check shock absorbers 32000			
G	Check engine mountings 22010			
G	Check subframe bushes 33010			
A	Check for general oil leaks 18000	Misting of oil to side of engine, looks to be rocker gaskets		
G	Check propshaft couplings condition 41015			

SL SHOP (Sales & Service) Ltd

Vehicle Health Check

CUSTOMER DETAIL

Mr Michael Bulgin
 H 01308 427651
 Tel M 07957 856 740
 W

VEHICLE DETAIL

Make Mercedes-Benz
 Model SL Class
 Registration C81HMD
 Chassis No WDB1070472A042497
 Mileage 90326

VHC NO

8891

Date 2022-11-30

Service Advisor

MOT Due 18/08/2023

Inspected By Russell Owens

Comments / Recommendations		Net	VAT	Total
G	Check fuel pump pipes/filter package 47045			
G	Check exhaust system condition 14060			
A	General underbody corrosion / Waxoyl 61000	O/s/f chassis leg/ towing eye surface corrosion, nsr arch to sill has a patch of exposed metal with surface corrosion. Would benefit from a waxoyl		
N/A	Visual check on brake pads and discs 42000			
N/A	Check rear drive shafts/boots 35030			
Soft Top Check 77000				
G	Check soft top open/closure/catch mechanism 7700	Hydraulic roof system fitted		
Water Test 00WT				
N/A	Check bulkhead for leaks			
N/A	Check window/door seals for leaks			
N/A	Check boot/rear lights for leaks			
Total		0.00	0.00	0.00

Tyres	Tread (mm)	Manufacturer	Size	Comments/Recommendations
G N/S Front				
G N/S Rear				
G O/S Front				
G O/S Rear				
G Spare				

Brakes	Drums	Pads	Discs	Comments/Recommendations
		% Remaining	% Remaining	
N/S Front	N			
N/S Rear	N			
O/S Front	N			
O/S Rear	N			

Photos

Customer Signature _____ The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.