

# SL SHOP (Sales & Service) Ltd

# Vehicle Health Check

## CUSTOMER DETAIL

Mr John Vowell  
H  
Tel M 07767 701025  
W

## VEHICLE DETAIL

Make Mercedes  
Model Pagoda  
Registration KJC228G  
Chassis No 11304412009366  
Mileage 58573

## VHC NO

8780

Date 2022-11-15  
Service Advisor Russell Owens  
MOT Due 04/11/2023  
Inspected By Russell Owens

Comments / Recommendations		Net	VAT	Total
<b>Initial Road Test 00IRT</b>				
G	Engine performance / smoke / noises			
G	Brake performance / spongy / pulling left or right			
G	Steering in straight position / feel / noises			
G	Check operation of warning lights 54585			
G	Check operation of wipers and washers 86000			
G	Check operation of horn 54105			
G	Check operation of parking brake 42120			
<b>lights 82000</b>				
R	Check operation of front external lights 82195	No front fog lights. The light switch inside vehicle pulls out as to operate fog lights. No fog lights visible on front or rear of vehicle.		
A	Check operation of rear external lights 82225	OS lamp lens has surface cracks.		
<b>Interior 91000</b>				
G	Check seat and seat belt operation 91090			
G	Check interior lights 82165			
G	Heater motor operation 83135			
A	Radio and aerial operation 82345	Intermittent loss of signal and sound cuts out when some other electrical components are in use.		
<b>Engine Bay 18000</b>				
G	Antifreeze strength 50000			
G	Remove heater box lid-check bulkhead 62015			
G	Check battery condition 54080			
G	Check charging Volts 15030			
G	Check G/Box oil level 18000			
G	Check engine oil level / condition 18000			
G	Check for fuel leaks 07075			
G	Check brake fluid level / condition 42000			
<b>Under Vehicle 00UV</b>				
G	Check drop links 32060			
G	Check front wishbones 33030			
G	Check shock absorbers 32000			
N/A	Check engine mountings 22010			
G	Check subframe bushes 33010			
A	Check for general oil leaks 18000	Evidence of oil loss from engine with drops forming on lower sections of engine.		
G	Check propshaft couplings condition 41015			

# SL SHOP (Sales & Service) Ltd

# Vehicle Health Check

## CUSTOMER DETAIL

Mr John Vowell  
 H  
 Tel M 07767 701025  
 W

## VEHICLE DETAIL

Make Mercedes  
 Model Pagoda  
 Registration KJC228G  
 Chassis No 11304412009366  
 Mileage 58573

## VHC NO

8780

Date 2022-11-15  
 Service Advisor Russell Owens  
 MOT Due 04/11/2023  
 Inspected By Russell Owens

Comments / Recommendations		Net	VAT	Total
G	Check fuel pump pipes/filter package 47045			
G	Check exhaust system condition 14060			
G	General underbody corrosion / Waxoyl 61000			
G	Visual check on brake pads and discs 42000			
G	Check rear drive shafts/boots 35030			
<b>Soft Top Check 77000</b>				
G	Check soft top open/closure/catch mechanism 7700			
<b>Water Test 00WT</b>				
G	Check bulkhead for leaks			
G	Check window/door seals for leaks			
R	Check boot/rear lights for leaks	Water ingress into boot, suspect split in boot seal		
<b>Total</b>		0.00	0.00	0.00

Tyres	Tread (mm)	Manufacturer	Size	Comments/Recommendations
G N/S Front				
G N/S Rear				
G O/S Front				
G O/S Rear				
G Spare				

Brakes	Drums	Pads	Discs	Comments/Recommendations
		% Remaining	% Remaining	
N/S Front	N			
N/S Rear	N			
O/S Front	N			
O/S Rear	N			

## Photos

**Customer Signature** \_\_\_\_\_ The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.