

SL SHOP (Sales & Service) Ltd

Vehicle Health Check

CUSTOMER DETAIL

Mr Michael Bucher
 H 07785303281
 Tel M
 W

VEHICLE DETAIL

Make Mercedes-Benz
 Model 380
 Registration CKH623X
 Chassis No 10702522003371
 Mileage 172966

VHC NO

9202

Date 2023-02-02
 Service Advisor
 MOT Due 07/05/2015
 Inspected By Russell Owens

Comments / Recommendations		Net	VAT	Total
Initial Road Test 00IRT				
G	Engine performance / smoke / noises			
G	Brake performance / spongy / pulling left or right			
G	Steering in straight position / feel / noises			
G	Check operation of warning lights 54585			
	Check operation of wipers and washers 86000			
G	Check operation of horn 54105			
G	Check operation of parking brake 42120			
lights 82000				
G	Check operation of front external lights 82195			
G	Check operation of rear external lights 82225			
Interior 91000				
A	Check seat and seat belt operation 91090	Drivers seat belt is a bit slow and noisy to retract		
G	Check interior lights 82165			
A	Heater motor operation 83135	Jammed heater slider n/s.		
A	Radio and aerial operation 82345	Electric aerial doesn't go all the way down.		
Engine Bay 18000				
G	Antifreeze strength 50000			
G	Remove heater box lid-check bulkhead 62015			
G	Check battery condition 54080			
G	Check charging Volts 15030			
N/A	Check G/Box oil level 18000			
G	Check engine oil level / condition 18000			
A	Check for fuel leaks 07075	All lines have been covered in waxoil		
G	Check brake fluid level / condition 42000			
Under Vehicle 00UV				
G	Check drop links 32060			
G	Check front wishbones 33030			
G	Check shock absorbers 32000			
G	Check engine mountings 22010			
G	Check subframe bushes 33010			
A	Check for general oil leaks 18000	Leak from back of engine suspect rear main and/or back of sump. N/S upper power steering hose is leaking		
G	Check propshaft couplings condition 41015			

SL SHOP (Sales & Service) Ltd

Vehicle Health Check

CUSTOMER DETAIL

Mr Michael Bucher
 H 07785303281
 Tel M
 W

VEHICLE DETAIL

Make Mercedes-Benz
 Model 380
 Registration CKH623X
 Chassis No 10702522003371
 Mileage 172966

VHC NO

9202

Date 2023-02-02
 Service Advisor
 MOT Due 07/05/2015
 Inspected By Russell Owens

Comments / Recommendations		Net	VAT	Total
G	Check fuel pump pipes/filter package 47045			
G	Check exhaust system condition 14060			
A	General underbody corrosion / Waxoyl 61000	Damage on o/s floor pan, been jacked up on or hit something. They have been waxoiled very thickly. Lots of surface corrosion to rear chassis legs,		
G	Visual check on brake pads and discs 42000			
A	Check rear drive shafts/boots 35030	Boots are very slightly perished, but will last for many years yet		
Soft Top Check 77000				
N/A	Check soft top open/closure/catch mechanism 7700			
Water Test 00WT				
N/A	Check bulkhead for leaks			
A	Check window/door seals for leaks	Window seals leak		
A	Check boot/rear lights for leaks	Rear light seals and cracked lense		
Total		0.00	0.00	0.00

Tyres	Tread (mm)	Manufacturer	Size	Comments/Recommendations
G N/S Front				
G N/S Rear				
G O/S Front				
G O/S Rear				
G Spare				

Brakes	Drums	Pads	Discs	Comments/Recommendations
		% Remaining	% Remaining	
N/S Front	N			
N/S Rear	N			
O/S Front	N			
O/S Rear	N			

Photos

Customer Signature _____ The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.